Report Identification	n: <u>20150818-01, 1234 Sampl</u>	e Street, Flower Mound, TX		
I=Inspected	NI=Not Inspected	NP=Not Present	D=Deficient	
I NI NP D				
		V. APPLIAN	CES	
	A. Dishwashers Comments: Component	(s) appear to be functioning	as intended.	
	Additional Comments necessarily related to	,	ction may contain photographs that	are not

NI=Not Inspected

I=Inspected NI NP D



D=Deficient

NP=Not Present

B. Food Waste Disposers Comments: Component(s) appear to be functioning as intended. C. Range Hood and Exhaust Systems Comments: Component(s) appear to be functioning as intended. D. Ranges, Cooktops, and Ovens Range Type: Electric

Comments: Component(s) functioning as intended, but minor deficiencies were observed.



I=Inspected	NI=Not Inspected	NP=Not Present	D=Deficient	
I NI NP D				

Additional Comments and Observations (This section may contain photographs that are not necessarily related to a deficiency.):

Cooktop photo. - "§535.232 (d)"



I=Inspected

NI=Not Inspected

NP=Not Present

D=Deficient

NI NP D



E. Microwave Ovens

Comments: Component(s) appear to be functioning as intended.

Additional Comments and Observations (This section may contain photographs that are not necessarily related to a deficiency.):



I=Inspected	NI=Not Inspected	NP=Not Present	D=Deficient			
I NI NP D						
	F. Mechanical Exhaust Vento Comments: Component(s	ts and BathroomHeaters s) appear to be functioning	g as intended.			
	G. Garage Door Operators Comments: Component(s) are deficient. Photographs included in this section are not representative of scope, frequency or severity. Items marked as deficient within this section may not have associated photographs included. If you have a question about the scope, frequency or severity of an item in this section, please contact your inspector.					
	The auto-reverse feature is not installed "§535.232 (g)"					
	H. Dryer Exhaust Systems Comments: Component(s	s) appear to be functioning	g as intended.			
	I. Other Comments:					